## Machine Guarding Pre/Post Test Answer Key

## Pre Test Answer Key

- 1. (D) Where work is performed on materials such as cutting, shaping, boring, or forming of stock.
- 2. (B) Transmits energy to the part of the machine performing the work.
- 3. (C) A point between rotating and fixed parts which shear, crush, or abrade.
- 4. (A) Is a repetitive up and down or back and forth linear motion.
- 5. (C) A circular saw
- 6. (D) All of the above
- 7. (B) Point of operation
- 8. (B) Fixed
- 9. (D) Attached to an operators hands and wrists, removed hands from POO
- 10.(B) False
- 11.(A) Awareness barriers, protective shields, and special hand tools
- 12.(C) A clear ring
- 13.(D) All of the above
- 14.(C) 30 PSI
- 15.(B) Employer

## Post Test Answer Key

- 1. (D) All of the above
- 2. (B) False
- 3. (A) Awareness barriers, protective shields, and special hand tools
- 4. (D) Where work is performed on materials such as cutting, shaping, boring, or forming of stock.
- 5. (C) A circular saw
- 6. (B) Transmits energy to the part of the machine performing the work.
- 7. (D) All of the above
- 8. (B) Fixed
- 9. (C) 30 PSI
- 10.(C) A point between rotating and fixed parts which shear, crush, or abrade.
- 11.(D) Attached to an operators hands and wrists, removed hands from POO
- 12.(C) A clear ring
- 13.(B) Point of operation
- 14.(B) Employer
- **15.**(A) Is a repetitive up and down or back and forth linear motion.

This material was produced under grant 46F6-HT30 from the Occupational Safety and Health Administration, U.S. Department of Labor. It does not necessarily reflect the views or policies of the U.S. Department of Labor, nor does mention of trade names, commercial products, or organizations imply endorsement by the U.S. Government. Revisions were made to this material under grant number SH- 31240-SH7 from the Occupational Safety and Health Administration, U.S. Department of Labor.