

# Six Ways to Stay Safe When Working in Marine Terminal Mechanic Shops

1

Ensure there is adequate lighting and ventilated work areas.



2

Keep walking and working surfaces clear and dry to prevent slips, trips, and falls.



3

Inspect tools, airline compressors, and equipment prior to use or operation.



4

Turn off, de-energize, and lockout and tagout all power sources before servicing equipment.



5

Follow safety requirements for flammable and combustible substances before performing hot work (see 29 CFR 1917.152).



6

Chock or brace wheels before servicing equipment. Never work under equipment that is not appropriately secured.

