

Withdrawn
Provided for Historical Reference Only

5. References

- 5.1. Taylor, D.C. (Manual Coordinator). "NIOSH Manual of Sampling and Analytical Methods". 2nd edition, U.S. DHEW/PHS/CDC/NIOSH, Vol. 2, 1977.
- 5.2. Faust, Charles L., Herman, Edward, CE, PH.D., "Charcoal Sampling Tubes for Organic Vapor Analysis by Gas Chromatography." American Industrial Hygiene Association Journal, 27 (January, 1966), 68-74.
- 5.3. Houghton, J.A., Lee, George, Shobaken, Marion A., and Fox, Anne. "Practical Applications of Analysis by the Ultraviolet Absorbance Method." American Industrial Hygiene Association Journal, 25 (July, 1964), 380-385.
- 5.4. Ede, Lorice (Editor). "Proceedings of NIOSH Styrene-Butadiene Briefing". U.S. DHEW/PHS/CDC/NIOSH. Washington, D.C., Government Printing Office, 1976.
- 5.5. Proctor, Nick H., Ph.D. and Hughes, James P., M.D. "Chemical Hazards of the Workplace". Philadelphia: J.B. Lippincott Company, 1978.
- 5.6. Stecher, Paul G. (Editor) "The Merck Index". 8th edition. Rahway: Merck and Company, Inc.
- 5.7. "Encyclopedia of Chemical Technology", 1969, 19, 55-83.
- 5.8. "The Condensed Chemical Dictionary", 1977, 9th edition, 821.

Note: OSHA no longer uses or supports this method (December 2019).