

Module 2, Scenario 6

A contract employee removing out-of-service lines in an old engine room accidentally cut into a live ammonia line. There was an uncontrolled release of ammonia throughout the facility. Employees #1 through #13 were hospitalized after ammonia inhalation.

