

U.S. Department of Labor
Occupational Safety and Health Administration
701 Lee Street
Suite 950
Des Plaines, IL 60016
Phone: 847-803-4800 Fax: 847-390-8220



Citation and Notification of Penalty

To:
Central Transport LLC
and its successors
12225 Stephens Road
Warren, MI 48089

Inspection Number: 966185
Inspection Date(s): 03/28/2014 - 09/24/2014
Issuance Date: 09/25/2014

Inspection Site:
200 N. Mannheim Road
Hillside, IL 60162

The violation(s) described in this Citation and Notification of Penalty is (are) alleged to have occurred on or about the day(s) the inspection was made unless otherwise indicated within the description given below.

This Citation and Notification of Penalty (this Citation) describes violations of the Occupational Safety and Health Act of 1970. The penalty(ies) listed herein is (are) based on these violations. You must abate the violations referred to in this Citation by the dates listed and pay the penalties proposed, unless within 15 working days (excluding weekends and Federal holidays) from your receipt of this Citation and Notification of Penalty **you either call to schedule an informal conference (see paragraph below) or** you mail a notice of contest to the U.S. Department of Labor Area Office at the address shown above. Please refer to the enclosed booklet (OSHA 3000) which outlines your rights and responsibilities and which should be read in conjunction with this form. Issuance of this Citation does not constitute a finding that a violation of the Act has occurred unless there is a failure to contest as provided for in the Act or, if contested, unless this Citation is affirmed by the Review Commission or a court.

Posting - The law requires that a copy of this Citation and Notification of Penalty be posted immediately in a prominent place at or near the location of the violation(s) cited herein, or, if it is not practicable because of the nature of the employer's operations, where it will be readily observable by all affected employees. This Citation must remain posted until the violation(s) cited herein has (have) been abated, or for 3 working days (excluding weekends and Federal holidays), whichever is longer.

Informal Conference - An informal conference is not required. However, if you wish to have such a conference you may request one with the Area Director during the 15 working day contest period. During such an informal conference you may present any evidence or views which you believe would support an adjustment to the citation(s) and/or penalty(ies).

If you are considering a request for an informal conference to discuss any issues related to this Citation and Notification of Penalty, you must take care to schedule it early enough to allow time to contest after the informal conference, should you decide to do so. Please keep in mind that a written letter of intent to contest must be submitted to the Area Director within 15 working days of your receipt of this Citation. The running of this contest period is not interrupted by an informal conference.

If you decide to request an informal conference, please complete, remove and post the Notice to Employees next to this Citation and Notification of Penalty as soon as the time, date, and place of the informal conference have been determined. Be sure to bring to the conference any and all supporting documentation of existing conditions as well as any abatement steps taken thus far. If conditions warrant, we can enter into an informal settlement agreement which amicably resolves this matter without litigation or contest.

Right to Contest – You have the right to contest this Citation and Notification of Penalty. You may contest all citation items or only individual items. You may also contest proposed penalties and/or abatement dates without contesting the underlying violations. **Unless you inform the Area Director in writing that you intend to contest the citation(s) and/or proposed penalty(ies) within 15 working days after receipt, the citation(s) and the proposed penalty(ies) will become a final order of the Occupational Safety and Health Review Commission and may not be reviewed by any court or agency.**

Penalty Payment – Penalties are due within 15 working days of receipt of this notification unless contested. (See the enclosed booklet and the additional information provided related to the Debt Collection Act of 1982.) Make your check or money order payable to “DOL-OSHA”. Please indicate the Inspection Number on the remittance. You can also make your payment electronically on www.pay.gov. On the left side of the pay.gov homepage, you will see an option to Search Public Forms. Type "OSHA" and click Go. From the results, click on **OSHA Penalty Payment Form**. The direct link is:

<https://www.pay.gov/paygov/forms/formInstance.html?agencyFormId=53090334>.

You will be required to enter your inspection number when making the payment. Payments can be made by credit card or Automated Clearing House (ACH) using your banking information. Payments of \$50,000 or more require a Transaction ID, and also must be paid using ACH. If you require a Transaction ID, please contact the OSHA Debt Collection Team at (202) 693-2170.

OSHA does not agree to any restrictions or conditions or endorsements put on any check, money order, or electronic payment for less than the full amount due, and will process the payments as if these restrictions or conditions do not exist.

Notification of Corrective Action – For each violation which you do not contest, you must provide ***abatement certification*** to the Area Director of the OSHA office issuing the citation and identified above. This abatement certification is to be provided by letter within 10 calendar days after each abatement date. Abatement certification includes the date and method of abatement. If the citation indicates that the violation was corrected during the inspection, no abatement certification is required for that item. The abatement certification letter must be posted at the location where the violation appeared and the corrective action took place or employees must otherwise be effectively informed about abatement activities. A sample abatement certification letter is enclosed with this Citation. In addition, where the citation indicates that ***abatement documentation*** is necessary, evidence of the purchase or repair of equipment, photographs or video, receipts, training records, etc., verifying that abatement has occurred is required to be provided to the Area Director.

Employer Discrimination Unlawful – The law prohibits discrimination by an employer against an

employee for filing a complaint or for exercising any rights under this Act. An employee who believes that he/she has been discriminated against may file a complaint no later than 30 days after the discrimination occurred with the U.S. Department of Labor Area Office at the address shown above.

Employer Rights and Responsibilities – The enclosed booklet (OSHA 3000) outlines additional employer rights and responsibilities and should be read in conjunction with this notification.

Notice to Employees – The law gives an employee or his/her representative the opportunity to object to any abatement date set for a violation if he/she believes the date to be unreasonable. The contest must be mailed to the U.S. Department of Labor Area Office at the address shown above and postmarked within 15 working days (excluding weekends and Federal holidays) of the receipt by the employer of this Citation and Notification of Penalty.

Inspection Activity Data – You should be aware that OSHA publishes information on its inspection and citation activity on the Internet under the provisions of the Electronic Freedom of Information Act. The information related to these alleged violations will be posted when our system indicates that you have received this citation. You are encouraged to review the information concerning your establishment at www.osha.gov. If you have any dispute with the accuracy of the information displayed, please contact this office.



NOTICE TO EMPLOYEES OF INFORMAL CONFERENCE

An informal conference has been scheduled with OSHA to discuss the citation(s) issued on 09/25/2014. The conference will be held by telephone or at the OSHA office located at 701 Lee Street, Suite 950, Des Plaines, IL 60016 on _____ at _____.

Employees and/or representatives of employees have a right to attend an informal conference.

CERTIFICATION OF CORRECTIVE ACTION WORKSHEET

Inspection Number: 966185

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162
Issuance Date: 09/25/2014

List the specific method of correction for each item on this citation in this package that does not read "Corrected During Inspection" and return to: **U.S. Department of Labor – Occupational Safety and Health Administration, 701 Lee Street, Suite 950, Des Plaines, IL 60016.**

Citation Number _____ and Item Number _____ was corrected on _____
By (Method of Abatement): _____

Citation Number _____ and Item Number _____ was corrected on _____
By (Method of Abatement): _____

Citation Number _____ and Item Number _____ was corrected on _____
By (Method of Abatement): _____

Citation Number _____ and Item Number _____ was corrected on _____
By (Method of Abatement): _____

Citation Number _____ and Item Number _____ was corrected on _____
By (Method of Abatement): _____

Citation Number _____ and Item Number _____ was corrected on _____
By (Method of Abatement): _____

I certify that the information contained in this document is accurate and that the affected employees and their representatives have been informed of the abatement.

Signature

Date

Typed or Printed Name

Title

NOTE: 29 USC 666(g) whoever knowingly makes any false statements, representation or certification in any application, record, plan or other documents filed or required to be maintained pursuant to the Act shall, upon conviction, be punished by a fine of not more than \$10,000 or by imprisonment of not more than 6 months or both.

POSTING: A copy of completed Corrective Action Worksheet should be posted for employee review



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 1 Item 1 Type of Violation: **Serious**

29 CFR 1910.23(a)(5): Every pit and trapdoor floor opening, infrequently used, was not guarded by a floor opening cover of standard strength and construction. While the cover is not in place, the pit or trap opening was not constantly attended by someone or was not protected on all exposed sides by removable standard railings:

a) Central Transport, LLC - On June 11, 2014, at bay #177, the floor opening in front of the dumpster was not guarded by a floor cover.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$3300.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

The alleged violations below have been grouped because they involve similar or related hazards that may increase the potential for injury or illness.

Citation 1 Item 2 a Type of Violation: **Serious**

29 CFR 1910.23(d)(1)(i): The employer did not provide a standard handrail on stairs with four or more risers:

a) Central Transport, LLC - The southeast fire exit stairs with five risers, next to bay #28, did not have a standard handrail.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:	10/15/2014
Proposed Penalty:	\$4400.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 1 Item 2 b Type of Violation: **Serious**

29 CFR 1910.24(f): All treads were not reasonably slip-resistant and the nosings were not of nonslip finish. Rise height and tread width were not uniform throughout any flight of stairs including any foundation structure used as one or more treads of the stairs:

a) Central Transport, LLC - The southeast fire exit stairs next to bay #28, the employer failed to ensure that the stair treads were reasonably slip resistant, and that the stair rise height and tread width were uniform throughout the flight of stairs including the foundation.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:

10/15/2014



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 2 Item 1 Type of Violation: **Willful**

29 CFR 1910.178(p)(1): Powered industrial truck(s) found to be in need of repair, defective, or in any way unsafe had not been taken out of service until restored to safe operating condition:

Central Transport, LLC - On March 28, 2014, the employer did not ensure that powered industrial truck(s) with defects or in any way unsafe were withdrawn from service until restored to safe operating condition in the following instances:

- a) The Yale Forklift #25-320, in need of repair had not been withdrawn from service, the tires were damaged, and one headlight was not working.
- b) The Yale Forklift #25-647, in need of repair had not been withdrawn from service, the tires were damaged, the parking brake pedal was missing a cover, the brakes were not properly engaging, and the battery charging cables had damage to the outer jacket.
- c) The Yale Forklift #23-269, in need of repair had not been withdrawn from service, one headlight was not working.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:	10/15/2014
Proposed Penalty:	\$60500.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 3 Item 1 Type of Violation: **Repeat**

29 CFR 1910.22(a)(2): Floor(s) of workroom(s) were not maintained in a clean and, so far as possible, a dry condition:

a) Central Transport, LLC - On March 28, 2014, the floors throughout the terminal dock and bay areas, were not clean, as they contained wood chips, cardboard, and wood from broken pallets, and were not maintained in a dry condition, due to an accumulation of rain water, from a leaking roof, lack of overhead doors, and the separation between the trailer.

Employees were exposed to floors which were not maintained clean and were not maintained in a dry condition, in the following instances:

- Instance 1: At the northwest forklift battery charging area, outside the dispatch office.
- Instance 2: North Bay Areas
- Instance 3: South Bay #55
- Instance 4: South Bay #57
- Instance 5-9: South Bay #59-63
- Instance 10-11: South Bay #66-67
- Instance 12: Near Bay #84-85
- Instance 13: At Bay #53

b) Central Transport, LLC - On June 11, 2014, the floors throughout the terminal dock and bay areas, were not clean, as they contained wood chips, cardboard, wood from broken pallets, and were not maintained in a dry condition, due to an accumulation of rain water, from a leaking roof, lack of overhead doors, and the separation between the trailer.

Employees were exposed to floors which were not maintained clean and were not maintained in a dry condition, in the following instances:

- Instance 14: At the southeast forklift battery charging area.
- Instance 15: At Bay #33
- Instance 16: At Bay #38

See pages 1 through 4 of this Citation and Notification of Penalty for information on employer and employee rights and responsibilities.



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

- Instance 17: At Bay #66-67
- Instance 18: Near Bay #66-67 (center dock area)
- Instance 19: At Bay #78
- Instance 20: Near Bay #78 (center dock area)
- Instance 21: At Bay #215
- Instance 22: At Bay #216

Central Transport, LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 29 CFR 1910.22(a)(2), which was contained in OSHA Inspection Number 77120, Citation Number 1, Item Number 1, and was affirmed as a final order on July 30, 2012, with respect to a workplace located at 200 North Mannheim Road, Hillside, IL.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$22000.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 3 Item 2 Type of Violation: Repeat

29 CFR 1910.23(c)(1): Open-sided floor(s) or platform(s) 4 feet (1.22 m) or more above the adjacent floor or ground level were not guarded by standard railings (or the equivalent as specified in 29 CFR 1910.23(e)(3)(i) through (v)), on all open sides:

- a) On or about March 28, 2014, at the Central Transport terminal, employees were exposed to fall hazards of approximately 4'-2", in the following instances;

Instance 1: The unguarded open sided floor on each side of the metal stair platform located at bay #57, was not guarded by a standard railing or its equivalent on all open sides.

Instance 2 and 3: At loading dock bays #60 and 75, were not guarded by a standard railing or its equivalent.

- b) On or about June 11, 2014, at the Central Transport terminal, employees were exposed to fall hazards of approximately 4'-2", in the following instances;

Instance 4: The unguarded open sided floor on each side of the metal stair platform located at bay #57, was not guarded by a standard railing or its equivalent on all open sides.

Instance 5, 6 and 7: At loading dock bays #48, 75 and 187, were not guarded by a standard railing or equivalent.

Central Transport LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 1910.23 (c)(1), which was contained in OSHA Inspection Number 950068, Citation Number 1, Item Number 1, and was affirmed as a final order on December 20, 2013, with respect to a workplace located at 150 Becknell Street, Pearl, MS.

Central Transport LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 1910.23 (c)(1), which was contained in OSHA Inspection Number 313631491, Citation Number 1, Item Number 2, and was affirmed as a final

See pages 1 through 4 of this Citation and Notification of Penalty for information on employer and employee rights and responsibilities.



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

order on September 14, 2010, with respect to a workplace located at 400 Childre Road, Pearl, MS.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$22000.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 3 Item 3 Type of Violation: **Repeat**

29 CFR 1910.151(c): Where employees were exposed to injurious corrosive materials, suitable facilities for quick drenching or flushing of the eyes and body were not provided within the work area for immediate emergency use:

Central Transport, LLC - On March 28, 2014, employees were exposed to injurious corrosive materials, and suitable facilities for quick drenching or flushing of the eyes and body were not provided within the work area for immediate emergency use.

- a) At the Southeast Battery Charging Station - The eyewash station was not accessible due to storage of truck tires and the water level was low and did not provide adequate flow.
- b) At the Northwest Battery Charging Station - The eyewash station was blocked by equipment and pallets containing freight, and the water level was low and did not provide adequate flow.

Central Transport, LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 29 CFR 1910.151(c), which was contained in OSHA Inspection Number 77120, Citation Number 2, item number 2, and was affirmed as a final order on July 30, 2012, with respect to a workplace located at 200 North Mannheim, Hillside, IL.

No abatement certification or documentation required for this item.

Date By Which Violation Must be Abated:	Corrected During Inspection
Proposed Penalty:	\$16500.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 3 Item 4 Type of Violation: **Repeat**

29 CFR 1910.176(g): Covers and/or guardrails were not provided to protect personnel from the hazards of open pits, tanks, vats, ditches, etc.:

a) Central Transport, LLC - On June 3, 2014, at the terminal roadway and yard, the employer did not protect personnel from potholes in the following instances:

Instance 1: Pothole 1, 2 - At the terminal entrance gate.

Instance 2: Pothole 3, 4 - At the terminal north roadway, west of the dispatch office and bay areas.

Instance 3: Potholes 7-8 - At the terminal north roadway, east of dispatch office, near bay 12.

Instance 4: Pothole 9 - At the terminal north roadway, outside of the ramp near east of the dispatch office, center road, contained a displaced drain cover, cracks and a drop in the pavement by 7 inches.

b) Central Transport, LLC - On June 11, 2014, at the terminal roadway and yard, the employer did not protect personnel from potholes in the following instances:

Instance 5: Pothole 10, 11 - At the terminal north roadway, east of the dispatch office, near bay 12.

Instance 6: Pothole 12, 13 - At the terminal north roadway, east of the dispatch office, near bay 12.

Instance 7-10: Potholes 14, 15, 16 and 17 - At the terminal north roadway, at the center, near bay 5 to 12.

Central Transport, LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 1910.176(g), which was contained in OSHA Inspection Number 950068, Citation Number 1, Item Number 2, and was affirmed as a final order on December 20, 2013, with respect to a workplace located at 150 Becknell Street, Pearl, MS.

See pages 1 through 4 of this Citation and Notification of Penalty for information on employer and employee rights and responsibilities.



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Central Transport, LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 1910.176(g), which was contained in OSHA Inspection Number 313631491, Citation Number 1, Item Number 6, and was affirmed as a final order on September 14, 2010, with respect to a workplace located at 400 Childre Road, Pearl, MS.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:	10/15/2014
Proposed Penalty:	\$16500.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 3 Item 5 Type of Violation: **Repeat**

29 CFR 1910.1200(h)(1): Employees were not provided effective information and training on hazardous chemicals in their work area at the time of their initial assignment and whenever a new hazard that the employees had not been previously trained about was introduced into their work area:

a) Central Transport, LLC - On March 28, 2014, the employer did not provide employees with effective information and training on hazardous chemicals in their work area at the time of their initial assignment, and whenever a new physical or health hazard was introduced into their work area. Employees were exposed to chemicals including;

Hawker lead-acid batteries containing 60% lead and 10-30% sulfuric acid; citric acid - anhydrous, pigment phthalo blue 15:3.

Central Transport, LLC, was previously cited for a violation of this Occupational Safety and Health Standard or its equivalent standard 29 CFR 1910. 1200(h)(1), which was contained in OSHA Inspection Number 77120, Citation Number 1, Item Number 8, and was affirmed as a final order on July 30, 2012, with respect to a workplace located at 200 North Mannheim Road, Hillside, IL.

In accordance with 29 CFR 1903.19(c), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET).

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$220.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 1 Type of Violation: **Other-than-Serious**

29 CFR 1910.22(b)(1): Where mechanical handling equipment was used, sufficient safe clearances were not allowed for aisles, at loading docks, through doorways and wherever turns or passage had to be made. Aisles and passageways were not kept clear and in good repair, with no obstruction across or in aisles that could create a hazard.

a) Central Transport, LLC - On or about June 11, 2014, where mechanical handling equipment was used, the work floors near bay #D206, were not kept in good repair.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:	10/15/2014
Proposed Penalty:	\$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 2 Type of Violation: **Other-than-Serious**

29 CFR 1910.23(e)(3)(iv): The anchoring of posts and framing of members for railings of all types were not of such construction that the completed structure was not capable of withstanding a load of at least 200 pounds applied in any direction at any point on the top rail:

a) Central Transport, LLC - On or about June 11, 2014, the anchoring posts and framing of members for railings were not of such construction that the structure was capable of withstanding a load of at least 200 pounds applied in any direction at any point on the top rail in the following instances:

- 1) The southeast fire exit stairs - at bay #57, the vertical posts were not anchored to the ground.
- 2) The northwest fire exit stairs - next to bay #190, the anchoring and framing were as follows;

The vertical posts and fastening bolts had visible signs of damage.
The west side handrail was bent and not connected at the bottom of the stringer.
The top hand rail, at the second vertical post was not anchored to the platform.
The left hand descending handrail, the vertical post at the base of the platform was not connected or anchored the stringer.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 3 Type of Violation: **Other-than-Serious**

29 CFR 1910.24(c): Fixed stairway(s) were not designed and/or constructed to carry a load of five times the normal live load anticipated or the strength to carry safely a moving load of 1000 pounds:

a) Central Transport, LLC - On or about June 11, 2014, the northwest fire exit stairs, next to bay #190, had damaged stringers due to rust at the first riser and first tread.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:	10/15/2014
Proposed Penalty:	\$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 4 Type of Violation: **Other-than-Serious**

29 CFR 1910.36(d)(1): Employee(s) were not able to open an exit route door from the inside at all times without keys, tools, or special knowledge:

a) Central Transport, LLC - The employer did not ensure that exit route doors were able to open from the inside at all times without keys, tools, or special knowledge in the following instances:

- 1) The northwest fire exit door next to bay #190 had a locking device.
- 2) The southwest fire exit door next to bay #103 had a locking device, and a device fastened at the bottom of the door and metal platform preventing the door from opening or closing.
- 3) The west fire exit door had a locking device (a panic bar) on the inside of the door.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 5 Type of Violation: **Other-than-Serious**

29 CFR 1910.37(a)(3): Exit route(s) were not kept free and unobstructed:

a) Central Transport, LLC - The employer did not ensure that exit routes were free and unobstructed in the following instances:

- 1) The southwest fire exit route next to bay #103, the exterior ground walking surface was littered with debris, wood, plastic strapping, cigarette butts, and wet cardboard.
- 2) The west fire exit route, the fire exit door had holes due to rust damage, and the panic bar contained a greasy substance.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 6 Type of Violation: **Other-than-Serious**

29 CFR 1910.151(b): Adequate first aid supplies were not readily available:

a) Central Transport, LLC - The employer did not ensure that the first aid kit, mounted outside of the dispatch office, next to the eyewash station was replenished.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated:
Proposed Penalty:

10/22/2014
\$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 7 Type of Violation: **Other-than-Serious**

29 CFR 1910.157(c)(1): Employer did not provide portable fire extinguishers which were mounted, located, and identified, so as to be readily accessible for employee use:

a) Central Transport, LLC - The employer did not ensure that portable fire extinguishers were mounted, located and identified so readily available for employee use.

On March 28, 2014, portable fire extinguishers were not readily available for employee use, in the following instances:

- Instance 1: Bay #60, the fire extinguisher was blocked by a garbage can containing garbage.
- Instance 2: Bay #75, the fire extinguisher was blocked by a garbage can containing garbage.
- Instance 3: Bay #84, the fire extinguisher was not mounted and maintained on the floor.
- Instance 4: Bay #56, the fire extinguisher was not available at the designated location.

On June 11, 2014, portable fire extinguishers were not readily available for employee use, in the following instances:

- Instance 5: Bay #12, the fire extinguisher was blocked by a garbage can containing garbage
- Instance 6: Bay #D232, the fire extinguisher was not mounted and maintained on the floor.
- Instance 7: Bay #210, the fire extinguisher was blocked by two load bars.
- Instance 8: Bay #217, the fire extinguisher was blocked by an orange cone.
- Instance 9: Bay #213, the fire extinguisher was blocked by two load bars.
- Instance 10: Bay #103, the fire extinguisher was not available at the designated location.
- Instance 11: Bay by Menlo operations, the fire extinguisher was not mounted and maintained on the floor.
- Instance 12: Bay by Menlo operations, the fire extinguisher was not readily accessible, due to the chain of an overhead door.
- Instance 13: Bay #1, outside the dispatch office, the fire extinguisher was blocked by a banding reel cart.
- Instance 14: At the ramp, outside the dispatch office, the fire extinguisher identification was not properly mounted and not visible due to soil accumulation on the sign.

See pages 1 through 4 of this Citation and Notification of Penalty for information on employer and employee rights and responsibilities.

U.S. Department of Labor
Occupational Safety and Health Administration

Inspection Number: 966185
Inspection Date(s): 03/28/2014 - 09/24/2014
Issuance Date: 09/25/2014



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records.

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$0.00

See pages 1 through 4 of this Citation and Notification of Penalty for information on employer and employee rights and responsibilities.



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162

Citation 4 Item 8 Type of Violation: **Other-than-Serious**

29 CFR 1910.178(l)(5): The employer did not evaluate the competency of the operator who had previously received training appropriate to the truck and working conditions encountered.

a) Central Transport, LLC - The employer did not ensure that all forklift operators were evaluated and found competent before assigning them to operate forklifts.

In accordance with 29 CFR 1903.19(d), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET), and in addition, documentation demonstrating that abatement is complete must be included with your certification. This documentation may include, but is not limited to, evidence of the purchase or repair of the equipment, photographic or video evidence of abatement, or other written records

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$0.00



Citation and Notification of Penalty

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162


Citation 4 Item 9 Type of Violation: **Other-than-Serious**

29 CFR 1910.1200(h)(3)(iv): Employee training did not include the details of the hazard communication program developed by the employer, did not include an explanation of the labels received on shipped containers and the workplace labeling system used by their employer; the safety data sheet, including the order of information and how employee could obtain and use the appropriate hazard information:

a) Central Transport, LLC - On March 28, 2014, the employer did not provide training on the revised Hazard Communication Standard, label elements and the new format and types of information on each section of Safety Data Sheets (SDSs) by December 1, 2013, and when employees are potentially exposed to hazardous chemicals and as required by the updated hazard communication standard.

In accordance with 29 CFR 1903.19(c), abatement certification is required for this violation (using the CERTIFICATION OF CORRECTIVE ACTION WORKSHEET).

Date By Which Violation Must be Abated: 10/15/2014
Proposed Penalty: \$0.00


Angeline Loftus
Area Director

U.S. Department of Labor
Occupational Safety and Health Administration
701 Lee Street
Suite 950
Des Plaines, IL 60016
Phone: 847-803-4800 Fax: 847-390-8220



INVOICE / DEBT COLLECTION NOTICE

Company Name: Central Transport LLC
Inspection Site: 200 N. Mannheim Road, Hillside, IL 60162
Issuance Date: 09/25/2014

Summary of Penalties for Inspection Number	966185
Citation 1, Serious	\$7700.00
Citation 2, Willful	\$60500.00
Citation 3, Repeat	\$77220.00
Citation 4, Other-than-Serious	\$0.00
TOTAL PROPOSED PENALTIES	\$145420.00

To avoid additional charges, please remit payment promptly to this Area Office for the total amount of the uncontested penalties summarized above. Make your check or money order payable to: "DOL-OSHA". Please indicate OSHA's Inspection Number (indicated above) on the remittance. You can also make your payment electronically on www.pay.gov. On the left side of the pay.gov homepage, you will see an option to Search Public Forms. Type "OSHA" and click Go. From the results, click on **OSHA Penalty Payment Form**. The direct link is <https://www.pay.gov/paygov/forms/formInstance.html?agencyFormId=53090334>. You will be required to enter your inspection number when making the payment. Payments can be made by credit card or Automated Clearing House (ACH) using your banking information. Payments of \$50,000 or more require a Transaction ID, and also must be paid using ACH. If you require a Transaction ID, please contact the OSHA Debt Collection Team at (202) 693-2170.

OSHA does not agree to any restrictions or conditions or endorsements put on any check, money order, or electronic payment for less than the full amount due, and will cash the check or money order as if these restrictions or conditions do not exist.

If a personal check is issued, it will be converted into an electronic fund transfer (EFT). This means that our bank will copy your check and use the account information on it to electronically debit your account for the amount of the check. The debit from your account will then usually occur within 24 hours and will be shown on

your regular account statement. You will not receive your original check back. The bank will destroy your original check, but will keep a copy of it. If the EFT cannot be completed because of insufficient funds or closed account, the bank will attempt to make the transfer up to 2 times.

Pursuant to the Debt Collection Act of 1982 (Public Law 97-365) and regulations of the U.S. Department of Labor (29 CFR Part 20), the Occupational Safety and Health Administration is required to assess interest, delinquent charges, and administrative costs for the collection of delinquent penalty debts for violations of the Occupational Safety and Health Act.

Interest: Interest charges will be assessed at an annual rate determined by the Secretary of the Treasury on all penalty debt amounts not paid within one month (30 calendar days) of the date on which the debt amount becomes due and payable (penalty due date). The current interest rate is one percent (1%). Interest will accrue from the date on which the penalty amounts (as proposed or adjusted) become a final order of the Occupational Safety and Health Review Commission (that is, 15 working days from your receipt of the Citation and Notification of Penalty), unless you file a notice of contest. Interest charges will be waived if the full amount owed is paid within 30 calendar days of the final order.


Delinquent Charges: A debt is considered delinquent if it has not been paid within one month (30 calendar days) of the penalty due date or if a satisfactory payment arrangement has not been made. If the debt remains delinquent for more than 90 calendar days, a delinquent charge of six percent (6%) per annum will be assessed accruing from the date that the debt became delinquent.

Administrative Costs: Agencies of the Department of Labor are required to assess additional charges for the recovery of delinquent debts. These additional charges are administrative costs incurred by the Agency in its attempt to collect an unpaid debt. Administrative costs will be assessed for demand letters sent in an attempt to collect the unpaid debt.



Angeline Loftus

Area Director



Date